



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

June 1, 2001

TO: Minerals File
FROM: Anthony Gallegos, Senior Reclamation Specialist *aa*
RE: Site Inspection, Lexco, Inc., ITM Mine, S/047/035, Uintah County, Utah

Date of Inspection: May 15, 2001
Time of Inspection: 1705 - 1735
Conditions: Mostly cloudy
Participants: Will Stokes, SITLA; Tony Gallegos, DOGM

Purpose of Inspection: To examine the site while in the area

There was no one else present at the site at the time of this inspection. Visible features at this site include a concrete shaft collar that has been filled in over the shaft, a concrete pad, a compressor tank, two 55-gallon drums, a second smaller concrete pad, a section of plywood wall, and an elevated fuel tank.

The two 55-gallon drums were both empty and labeled "XTRA - Wet Concentrate." This is a wetting agent for gilsonite produced by IBEX Chemicals, Inc. There were two more drums on the ground down below the main pad level. There is another 55-gallon drum mounted on a stand, which is lying down on the ground.

A short distance from the main shaft is a head frame located on the escapeway shaft with a small shack nearby. The escapeway shaft is also capped with concrete.

Photographs were taken to document the remaining features at the site and the site conditions. The site appears to be in the cleanup and closure stage.

jb
cc: Jim Lekas, Lexco, Inc.
Will Stokes, SITLA
S47-35-ins.doc

XCO - ITM

9/047/035

